




Pos. 1
2 x RE 40 - 250W
L=1000




Pos. 2
2 x Seitenabd.
für RE 40 - 250W




Pos. 3
2 x PS 60 x 40
links




Pos. 4
2 x PS 60 x 40
rechts




Pos. 5
2 x PP 50
L=416




Pos. 6
4 x PP 50
L=840




Pos. 7
1 x PP 50
L=440




Pos. 8
2 x PP 50
L=416



Pos. 9
1 x PP 50
L=440




Pos. 10
4 x Kunststofffuß
oder
4x Rollen




Pos. 11
16 x d=9,5



Pos. 12
12 x M6 DIN 508
13mm




Pos. 13
28 x M6 x 25
DIN 6912




Pos. 14
8 x M6 x 8
DIN 7380




Pos. 15
4 x M6 x 40 A2
DIN 7380



Pos. 16
4 x DIN 125
Ø 11



Pos. 17
4 x DIN 936
M 10




Materialliste
Maschinentisch L = 1000


Art. Nr. 248 550 0010

1


Fuß rechts




Fuß links




2



2




3




Montageanleitung
Maschinentisch L = 1000

Art. Nr. 248 550 0010


4



5



6



Montageanleitung
Maschinentisch L = 1000

Art. Nr. 248 550 0010